


VERSAILLES CROWN CORNER INSTALLATION



Step 1. Cut Moulding in half.



Step 2. Cut each half, in half again.



Step 3. & 4. Using either a compound miter box or hand saw, cut each piece at 45 degree angle using the molded tab as a guide.



Step 5. Fine sand the cut edges and assemble.